

## **EPA Potential Hazardous Waste Site Identification Region 6**

EPA's Hazardous Waste Site I actually exists.	Ith or environmental threat exists Enforcement and Response Syste		essed under
A. SITE NAME  Arkansas Zinc Smelting Company			CERCLIS ID NUMBER:
Arkansas Zinc Smelting Co	ompany		42NOOO607488
B. LOCATION (coordinates or exact st	reet address)		
3101 Kibler Road			
C. CITY	D. STATE	E. ZIP CODE F	COUNTY NAME
Van Buren	AR	72956	Crawford
G. OWNER/OPERATOR (if known)  1. NAME  2. TELEPHONE NUMBER			
The current property owner is Deadwood Lake LLC and Jay Gipson			NA
H. TYPE OF OWNERSHIP (if known)			
☐ FEDERAL ☐ STATE	☐ COUNTY ☐	MUNICIPAL 🛛 F	PRIVATE UNKNOWN
NATIVE AMERICAN INTERES	T ☐ Yes ⊠ No Ifyes	s, which tribe(s):	·
I. SITE DESCRIPTION		<u></u>	
This former zinc smelter is on a 22.4 acre plot and is surrounded by a mix of industrial and residential areas. During its time as a smelter, the facility had multiple furnaces, kilns, and a lab. Most recently, the facility was used as a feed mill and the property now consists of multiple silos and storage areas. The age of this site and the dates of ownership changes have not yet been determined, but it appears that the site has been vacant since November of 2009.			
The age of this site and the	dates of ownership cha	nges have not yet beer	ple silos and storage areas. n determined, but it appears
The age of this site and the	dates of ownership cha	nges have not yet beer 09.	ple silos and storage areas.  n determined, but it appears  K. DATE IDENTIFIED
The age of this site and the that the site has been vaca	dates of ownership cha	nges have not yet beer 09.	n determined, but it appears
The age of this site and the that the site has been vaca	e dates of ownership cha ant since November of 20	nges have not yet beer 09.	determined, but it appears  C. DATE IDENTIFIED
The age of this site and the that the site has been vaca  J. HOW IDENTIFIED  Sanborn Maps  L. SUMMARY OF POTENTIAL OR KN  Former heavy metal smelte The site has been in indus in operation is currently un 1923 through 1930. Histor been recorded. Water, air, Additionally, a 20,000 galle has since been removed.	e dates of ownership cha int since November of 20 OWN PROBLEM ers are some of the worst trial operation since at le nknown, although smeltin ical complaints about ver and regulated storage ta on underground diesel ta	nges have not yet beer 09.  contributors to heavy ast 1923. The exact peng operations appear to getation kills related to ink permits had been is nk was associated with sment of the actual an	metal pollution. eriod of time the smelter was a have occurred from at least a smelter emissions have ssued for the feed mill.
The age of this site and the that the site has been vaca  J. HOW IDENTIFIED  Sanborn Maps  L. SUMMARY OF POTENTIAL OR KN  Former heavy metal smelter  The site has been in industin operation is currently under the site has been in industin operation. History been recorded. Water, air, Additionally, a 20,000 galled has since been removed.  ADEQ recommends a commends a commends.	e dates of ownership cha ant since November of 20 OWN PROBLEM ers are some of the worst trial operation since at le nknown, although smeltin ical complaints about ver and regulated storage ta on underground diesel ta plete and accurate asses on of human health and t	nges have not yet beer 09.  contributors to heavy ast 1923. The exact peng operations appear to getation kills related to ink permits had been is nk was associated with sment of the actual an	metal pollution.  ariod of time the smelter was be have occurred from at least smelter emissions have ssued for the feed mill.  a the feed mill, although it



670913